


5 Larkin factory shipping office, E and E buildings, 1901. (The Larkin Idea, May-November 1901, p. 40)



6 Larkin factory In-Mail Department, E and F buildings, 1901. (The Larkin Idea, May-November 1901, p. 37)










60 Metal desk with magnesite panels. (Courtesy The Frank Lloyd Wright Memorial Foundation)

in metal, an additional fireproofing measure. Three different types of desks and four different types of chairs, as well as filing cabinets and lighting fixtures, were fabricated to Wright's designs by the Van Dorn Iron Works of Cleveland, Ohio.12 The rectangular chairs and desks were made of folded and punched sheet steel riveted somewhat like the framing of a building. The freestanding office chairs with castiron bases (see Fig. 49) were exceptionally heavy.13 Wright was proud of the easy cleaning made possible by his design for folding chairs that cantilevered from most metal desks (Figs. 61, 62), but in use these chairs allowed only a limited arc of movement and may have been uncomfortable over the course of a full workday. Wright's three-legged office chair was so unstable that it became known as the "suicide chair" among office personnel. These problems led to a minor insurrection in 1913 when some department heads threatened to import more comfortable wooden chairs on their own.4 The Larkin executives were able to quell this uprising, but it indicates that Wright considered appearance before comfort in his furniture design.

Wright promised Darwin Martin that the new ad-



61 Metal desk with attached chair in open position.



Metal desk with attached chair folded.










41 The In-Mail Department, third floor. (Courtesy The Frank Lloyd Wright Memorial Foundation)



































The Evolution and Sources of the Design 29 REVISED APRIL 1, 1904 LATE 1903 . FINAL DESIGN GROUP 3 PRELIMINARY


21 Evolution of corners of the Larkin Building from early 1903 to April 1, 1904. (Drawn by James Cahill)






37 Fourth-floor schematic plan of mail room setting arranged by States. (Drawn by James Cahill)






THIRD FLOOR


38 Third-floor schematic plan showing location of In-Mail Department and mail-order state groups. (Drawn by James Cahill)




MAIN FLOOR

charteness of the second 1 0000 000 die जी:16 ENTIETO INTHO CFFICE BUILDING
THE LADKIN SOAPCO
BUFFALO HEW YORK
FRANK-LLPYD WINGHT
ARCHITECT CHICAGO FIRST FLOOR PLAN HANTENH BELOW WINDOW SILLS ----MALE PLAN ABOVE MINDOW SILLS S NO COLUMN TO COLUMN TO CAMPA 1






























































Frank Lloyd Wright, Abraham Lincoln Center, hicago, Illinois, first elevation, ca. 1899. (Architectural eview [Boston], 7, June 1900, p. 72)




13 Louis Sullivan, Wainwright Building, Saint Louis, Missouri, 1890-91. (Historic American Buildings Survey)










9 Larkin Administration Building, Seneca Street elevation, first set of preliminary drawings, early 1903. (Grant C. Manson, Frank Lloyd Wright to 1910: The First Golden Age, New York, 1958, Fig. 968)





10 Seneca Street elevation, second set of preliminary drawings, early 1903. (& The Frank Lloyd Wright Foundation, 1987. Courtesy the Frank Lloyd Wright Memorial Foundation)





n Seneca Street elevation. (Courtesy The Frank Lloyd Wright Memorial Foundation)























Larkin Building: cut-away drawing showing location of main air-ducts.


Fresh air intake


- Tempered air distribution
 Foul air and exhaust
- 4. Utilities duct
- 5. Tempered air outlet grilles under edge of balconies




















791 Larkin Building and plan